This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

Inamura et al.
Greer, Burns & Crain, Ltd. (Patrick G. Burns)
Sheet 1 of 6 (312) 360-0080

FIG.1A




FIG.1B





FIG.2



Greer, Burns & Crain, Ltd. (Patrick G. Burns) Sheet 3 of 6 (312) 360-0080

FIG.3A





FIG.3B




MAGNETIC RECORDING MEDIUM... 3/26/04
Inamura et al.
Greer, Burns & Crain, Ltd. (Patrick G. Burns)
Sheet 4 of 6 (312) 360-0080

FIG.4

•	conventional 2-layer medium	present 2-layer medium
noise caused by magnetic recording layer	yes	yes
noise caused by backing layer	yes	no

MAGNETIC RECORDING MEDIUM... 3/26/04
Inamura et al.
Greer, Burns & Crain, Ltd. (Patrick G. Burns)
Sheet 5 of 6 (312) 360-0080

FIG.5



(B)

FIG.6A




FIG.6B

